

LI - ION 18V CORDLESS DRILL BT-CD 18/1 Li

QUICK START GUIDE

Easy steps to getting started.

- 1. Read the User Guide for all SAFETY aspects of using your TAURUS TITANIUM ® 18 V CORDLESS DRILL.
- 2. Carefully remove the 18 V CORDLESS DRILL from the packaging, take care that you have all parts supplied in the packaging before discarding.
- 3. Press the pushlock button (5) to remove the battery pack (4) from the handle.
- 4. Plug the mains plug of the charger into the mains socket outlet.
- 5. Connect the charging cable to the charging adapter. Both LED's are lit.
- 6. Push the charging adapter onto the battery pack (4). The green LED will go out and the red LED will go on. Once the charging process is completed (approx. 3 to 5 hours), both LED's will come on again. **NOTE:** At temperatures below 0°C the battery will not be charged.
- 7. For screwdriving select the torque with the torque selector (1), refer to the User Guide, Section 6.8 for more information. **Important!** The tool must be at a standstill when you set the torque with the setting ring.
- 8. For drilling, move the torque selector (1) to the last step "Drill".
- 9. Use the Forward/Reverse switch (2) to select the direction of rotation.
- 10. You can adjust the speed. The further you press the On/Off switch (3), the higher the speed.
- 11. To change the accessory, open the chuck (7) by turning it counterclockwise. Place the accessory into the tool and tighten the chuck by turning it clockwise. **Important!** Set the Forward/Reverse switch (2) to its centre position whenever carrying out any work on the tool.
- 12. By adjusting the selector switch (6), you can work with a faster or slower turning speed.
- 13. To see the charge state of the battery, press the button for the battery capacity indicator (11). (Refer to User Guide, Section 6.6 for more details).
- 14. IF IN DOUBT PLEASE REFER TO THE USER GUIDE PROVIDED.



